

Product Discontinuation Notice

Mercury Relays

Dear customer,

We would like to inform you that due to both the worldwide trend of Restriction of Hazardous Substances (RoHS) and a lower customer demand, Standex Electronics will discontinue production of relays that contain a Mercury Wetted Switch "31" or "88". The product discontinuation is **effective 1st May 2021** and affects the following product(s):

Discontinued Part Numbers				Direct Replacement	Alternative Part Number
SILxx-1A31-xxx	DILxx-2A31-xxx	BExx-1B31-xxx	MRExx-1B31-xxx	n/a	Dry Relay Series, please contact Standex for support
DIPxx-1A31-xxx	Llxx-1A31	BExx-1B88-xxx	MRExx-1B88-xxx		
DIPxx-2A31-xxx	BExx-1A31-xxx	BExx-2A31-xxx	MRExx-2A31-xxx		
DILxx-1A31-xxx	BExx-1A88-xxx	BExx-2A88-xxx	MRExx-2A88-xxx		

Last Time Buy is dependent on the particular relay type. Please contact the nearest sales office for more details.

There is not any direct replacement available by Standex Electronics, however it is possible to use another standard relays with Dry Switch as an alternative solution to enable the same functionality.

See: [Reed Relays & Optocouplers | Standex Electronics](#)

For additional technical support and questions regarding an alternative solution, please contact Mr. David Stastny (dstastny@standelectronic.com)

David Stastny
Product Manager
Reed Relays & Optocouplers

DocuSigned by:
David Stastny
D4D8731487A3463...

Daniel Küchler
Senior Business Development
Manager

DocuSigned by:
Daniel Küchler
666039BC67B74B8...

Ralf Maier
Vice President &
General Manager SST

DocuSigned by:
Ralf Maier
6BE1FA8238C649C...