


Product Discontinuation Notice

RM05-4AS



Dear customer,


We would like to inform you that due to both the unavailability of key production materials and lower customer demand that **effective 30 September 2020** Standex Electronics will discontinue the following product(s):

Discontinued Part Number	Discontinued Item #	Product Type	Direct Replacement	Alternative Part Number
RM05-4AS-4/4	9605480020	Reed Relay	n/a	CRF05-1A (4 each)
RM05-4AS-4/2	9605480120	Reed Relay	n/a	CRF05-1A (4 each)


Unfortunately due to the unavailability of production materials we are unable to offer a last time buy. There is no direct replacement available by Standex Electronics however it is possible to use 4 individual CRF series reed relays as an alternative solution to enable the same functionality.

For additional technical support and questions regarding an alternative solution, please contact Mr. David Stastny (dstastny@standexelectronics.com)

David Stastny
Product Manager
Reed Relays & Optocouplers

DocuSigned by:

D4D8731487A3463...

Daniel Küchler
Senior Business Development
Manager

DocuSigned by:

666039BC67B74B8...

Ralf Maier
Vice President &
General Manager SST

DocuSigned by:

6BE1FA8238C649C...